





GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:					
Company	Dave Shaver				
OGM	Karl Houskeeper				

Inspection Report

Permit Number:	C0150032				
Inspection Type:	PARTIAL				
Inspection Date:	Thursday, December 02, 2010				
Start Date/Time:	12/2/2010 8:00:00 AM				
End Date/Time:	12/2/2010 1:30:00 AM				
Last Inspection:	Wednesday, November 03, 2010				

Inspector: Karl Houskeeper,
Weather: Clear, Temp.25 Deg. F.
InspectionID Report Number: 2577

Accepted by: jhelfric 12/9/2010

Permitee: GENWAL RESOURCES INC
Operator: GENWAL RESOURCES INC
Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

6,235.80	Total Permitted		
27.15	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

County

Fee

Other

✓ Federal✓ State

✓ Underground

Surface

Loadout
Processing

Types of Operations

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Checked with Dave Shaver at the Main Office and then proceeded to the Crandall Mine. Dave was not able to be present during the inspection.

Inspector's Signature:

Hart. Louskaper

Date Thursday, Dece

ecempNR²⁰¹⁰

OU GAS & MINING

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Thursday, December 02, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		~	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	V	✓		
6.	Disposal of Excess Spoil, Fills, Benches	✓	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V	✓		
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	~		V	

Inspection Continuation Sheet

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Thursday, December 02, 2010

Page 3 of 3

2. Signs and Markers

The mine identification sign is in place at the point of contact into the permit permit area from public access. The sign contains the required information.

22. Other

Mine site is covered by a light blanket of snow. The main road way into the site has been plowed. The diversions remain open.